	Туре	L #	Hits	Search Text
1	BRS	L1	18155	(soil dirt).clm.
2	BRS	L2	420	1 and (load strain stress force pressure) near2 (cell gauge guage sens\$5 detect\$5 transducer measur\$5).clm.
3	BRS	L3	70	2 and (bridge)
4	BRS	L4	50	3 and (depth)
5	BRS	L5	8	4 and (torque)
6	BRS	L6	212	depth near2 tillage
7	BRS	L7	6	6 and (load strain stress force pressure) near2 (cell gauge guage sens\$5 detect\$5 transducer measur\$5).clm.

	DBs	Time Stamp	Comments	Error Definition	Erro rs
1	USPAT; US-PGPUB; EPO; JPO; DERWENT	2004/08/12 12:04			0
2	USPAT; US-PGPUB; EPO; JPO; DERWENT	2004/08/12 12:24			0
3	USPAT; US-PGPUB; EPO; JPO; DERWENT	2004/08/12 12:06			0
4	USPAT; US-PGPUB; EPO; JPO; DERWENT	2004/08/12 12:06			0
5	USPAT; US-PGPUB; EPO; JPO; DERWENT	2004/08/12 12:24			0
6	USPAT; US-PGPUB; EPO; JPO; DERWENT	2004/08/12 12:24			0
7	USPAT; US-PGPUB; EPO; JPO; DERWENT	2004/08/12 12:25			0

	Туре	L#	Hits	Search Text	DBs
1	BRS	L3	748	Shibusawa.in.	USPAT; US-PGPUB; EPO; JPO; DERWENT
2	BRS	L1	6	"5524560"	USPAT; US-PGPUB; EPO; JPO; DERWENT
3	BRS	L2	13	"6041582"	USPAT; US-PGPUB; EPO; JPO; DERWENT
4	BRS	L4	44	Upadhyaya.in.	USPAT; US-PGPUB; EPO; JPO; DERWENT
5	BRS	L5	2	3 and (depth).clm.	USPAT; US-PGPUB; EPO; JPO; DERWENT
6	BRS	L6	1	5 and (load force strain stress pressure) near2 (cell gauge guage transducer sensor detector)	USPAT; US-PGPUB; EPO; JPO; DERWENT

	Time Stamp	Comments	Error Definition	Erro rs
1	2004/08/12 13:27			0
2	2004/08/12 13:21			0
3	2004/08/12 13:24			0
4	2004/08/12 13:25			0
5	2004/08/12 13:28			0
6	2004/08/12 13:29			0